

GOVERNMENT OF ANDHRA PRADESH
ABSTRACT

Secretariat Buildings – General Administration Department –
Replacement of existing Fire Extinguishers with new ones in Hon'ble
Chief Minister's Office, 6th Floor, C-Block in the premises of Secretariat,
Hyderabad – Administrative Sanction – Orders – Issued.

=====

GENERAL ADMINISTRATION (SB.I) DEPARTMENT
G.O.Rt.No. 3313 Dated 18.07.2012
Read:-

From the Electrical Engineer (GI), R&B, Lr No. EE/GL/HD/DB/TA2/2012-
13 / 1378, Dated 04.07.2012)

ORDER:

In the circumstances reported by the Electrical Engineer (Genl),
R&B, AC Guards, Hyderabad in the reference read above and after
examination, Government is hereby accorded administrative sanction for
an amount of ` . Rs.2,30,000.00 (Rupees Two Lakhs thirty thousand only)
for the work Replacement of existing Fire Extinguishers by fixing 12 Nos.
2 Kg fire extinguishers and 1 No 4 Kg fire extinguisher in Hon'ble Chief
Minister's Office, 6th Floor, C-Block in the premises of Secretariat,
Hyderabad on the responsibility of Electrical Engineer (Genl), R&B, AC
Guards, Hyderabad subject to following due procedure and also subject
to production of the work done certificate at the time of issue of L.O.C.

2. The expenditure shall be debited to the head of account "2059
Public works - 01 Office buildings - MH 053 Maintenance and repairs –
SH(10) Buildings of General Administration Department - 270 Minor
works - 272 Maintenance"

3. This order does not require the concurrence of Finance Department
as per rules in force.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

AJAY MISRA
PRINCIPAL SECRETARY TO GOVERNMENT (POLL)

To:
The Electrical Engineer (General), R&B, AC Guards, Hyderabad.
The Dy. Executive Engineer (Electrical), Sectt. Sub-division, Hyderabad.
SF/SC.

// Forwarded : : By Order //

SECTION OFFICER